

An exploded view diagram of a mechanical assembly. The components are arranged in a sequence from left to right, showing their relative positions and assembly order. The parts include:

- A green rectangular frame with a central cutout and four mounting holes (top left).
- A black circular flange with four mounting holes (middle left).
- Two brown cylindrical components (bottom left).
- A small silver rectangular plate (bottom left).
- Two silver cylindrical components (bottom left).
- A yellow rectangular frame with a central cutout and four mounting holes (bottom center).
- A black circular flange with four mounting holes (bottom center).
- A green rectangular frame with a central cutout and four mounting holes (bottom right).
- A series of black and grey cylindrical components (top center).
- Two large black oval components (top right).