

Metelli - 240579 - Bomba de agua

Tipo de servicio: mecánico

Se requiere adicionalmente artículo N° 24-1105 reinforced

Artículo complementario/ Información complementaria 2: con anillo retención para bomba de agua

AUDI

026 121 010FX
068 121 010AX
068 121 010A
037 121 010A
037 121 010
026 121 010X
026 121 010V
026 121 010FV
026 121 010
026 121 010F
026 121 010C
026 121 010CV

FORD

1031879

SEAT

037 121 010
037 121 010A
026 121 010F

SKODA

037 121 010A
037 121 010
026 121 010F

VW

026 121 010FV
068 121 010AX
026 121 010F
068 121 010A
037 121 010
037 121 010A
026 121 010X
026 121 010CV
026 121 010FX
026 121 010V

026 121 010C

026 121 010





